

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
  - TEXT CUT OFF AT TOP, BOTTOM OR SIDES
  - FADED TEXT
  - ILLEGIBLE TEXT
  - SKEWED/SLANTED IMAGES
  - COLORED PHOTOS
- 
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
  - GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.



Figure 1

**Lucent Technologies**  
Bell Labs Innovations

# Microelectronics Group

## 2. Cu<sub>3</sub> CMP




FIGURE 2

## 3. Metals and MOM oxide deposition




FIGURE 3


Fig. 2&3

Lucent Technologies Inc..

Lucent Technologies  
Bell Labs Innovations




## 5. Metal and oxide etch




**Lucent Technologies Inc..**



## 8. Another version of doublemnom

[illegible]




**Fig. 9**

**Lucent Technologies Inc..**

FILED



Figure 10  
250



**Lucent Technologies Inc..**